Oil Field Environmental Incident Summary

Responsible Party: BOW PETROLEUM, INC. OF COLORADO **Well Operator:** BOW PETROLEUM, INC. OF COLORADO

Well Name: JOHNSON 1

Field Name: PLAZA Well File #: 13006

Date Incident:6/21/2016Time Incident:22:00Facility ID Number:County:MOUNTRAILTwp: 152Rng: 88Sec: 6Qtr:

Location Description:

Submitted By: Ross Unruh Received By:

Contact Person: Ross Unruh

5435 SOUTH PRINCE STREET LITTLETON, CO 80120-1123

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
200 Barrels 200 Barrels 200 barrels

Oil Brine

Other

Description of Other Released Contaminant:

Oil

Inspected: Written Report Received: 1/12/2017 Clean Up Concluded: 10/1/2016

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Remove oil from containment area the surface and place into the tanks. Excavate contaminated soil and dispose in the proper facility. Replace with we will fresh soil and gravel to bring the facility and containment area back to normal.

Wastes Disposal Location: To be determined unsure of location of proper disposal facility.

Agencies Involved: Local Fire Department

North Dakota State Oil and Gas

Updates

Date: 6/22/2016 Status: Reviewed - Follow-up Required Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to amount lost, follow-up is required.

Date: 6/28/2016 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 4:30, 6/28/2016.

No sign of impacts off of location. NO PHOTOS TAKEN.

No follow-up is necessary.